


Beaded Banner Kit

Materials needed:
(bell pull banner)




Helpful Hints


- Read all instructions before beginning.
- Keep thread tension taut.
- Align beads with pattern sheet after each row.
- When approximately 6" of thread is left on needle attach new thread in 2 yd. lengths, using a square knot.
- To restore finish to beads, rub with a small amount of mineral oil.

Questions ?
1-800-422-4472
info@thebeadery.com
www.thebeadery.com


- 1** Cut 2yds. of thread and thread needle. Cut out pattern on dotted lines. Align and tape two halves together.




- 2** Tape pattern to work surface. Tape 6" of thread to left side of row 1. Thread on 25 beads. These beads will become rows 1 and 2.




- 3** Slide metal rod through every other bead to form rows 1 and 2.




- 4** Slide end caps onto rod. Tape rod to pattern close to end beads.




- 5** String on the first bead in row 3. Pass needle through last bead in row 2 to secure.




- 6** Continue adding and securing beads one at a time until row 3 is complete.




- 7** Remove tape from thread. Tie threads together using a square knot. Glue knot, pass threads through last bead added and trim excess. Complete rows 4 & 5.




- 8** Pass needle through outer edge thread. Pass back through last bead added and continue project through row 122. (Note: This step must be completed for all left side turns.)




- 9** After last bead of row 122, pass needle up through end bead of previous row. Pass needle through outer edge thread...




- 10** ...and back through beads as shown.



- 11** Continue across row. After last bead, go up through end bead of previous row, then around thread as shown.




- 12** Pass needle back through both beads and continue across row.






- 13** After last bead, go up through end bead of previous row, then around thread and back through both beads as shown.




- 14** Continue through row 133, tapering at each end as shown in steps 11-13.



- 15** To end, add last bead and go up through end bead of previous row. Make end knot by passing needle around thread and back through loop as shown. Make sure beads are nested together and pull tight. Repeat end knot. Glue and trim excess thread.



- 16** Attach cord to metal rod and pull knots tight to secure.



THE BEADERY®
CRAFT PRODUCTS

P.O. Box 178
Hope Valley, RI 02832 USA